





INSTALL DRAWING



PG-B19H-SD12	Installation tool			
	  			
	Installs the hardware			
	No.	Accessories	No.	Accessories
	S1	 4x16=52	S2	 4x20=10
1. 700×357×16=1				
2. 1148×700×16=1				
3. 700×398×25=2				
4. 1200×400×25=2				
5. 756×357×25=1	S3	 x38	S4	 x38
6. 696×380×16=2	S3	 x38	S4	 x38
7. 345×100×16=2	S5	 x16	S6	 x5
8. 317×85×16=2	S5	 x16	S6	 x5
9. 350×326×5=2	S7	 x4	S8	 x4
10. 380×152×16=1	S7	 x4	S8	 x4
11. 345×140×16=4	S9	 x2	S10	 x2
12. 317×125×16=2	S9	 x2	S10	 x2
13. 380×270×16=2		 3.5×14=36 x3		 4x40=12

Important: Follow steps on order. Requires 2 people to complete assembly